

**Customer Name:** 

Addr:

E Mail:

# Checkpoint Home Inspection LLC 21 E Crescent Ave Ramsey NJ 07446 551-777-3774 NJ Lic.# 24GI00\*\*\*\*00 Radon MET\*\*\*\*\*

#### Quick Report/Pre-List Inspection

State:

Email:

Zip:



Weather Cor	idition -Si	iow Si	ın Clo	udy Rain	
			Stı	ructure	
Foundation Type	Exterior Wall Construction				
☐ Poured Concrete			Joists		□Masonry
☐Masonry Block			Trusses		☐Wood Frame
			□ Concrete		☐Wood Frame, Brick
					Veneer
Stone			■Not Visible		Log
Brick			Engineer	ed I beams	☐Post and Beam
Piles and Grade B	eams				☐Not Visible
Piers			Configurat	ion	
□Wood			Basemen	t	Roof and Ceiling Frame
☐ Not Visible			Crawl Sp		☐Rafters/Roof Joists
Other			☐Slab-on-0	Grade	□Trusses
					□Not Visible
Restricted/Limited Access Areas	Inspected from Access Hatch	Entered but Access was	No Access or Not Available	Finished/Concealed	NOTES:
	Only	limited			
Crawl Space			$\bot$		
Basement					
Knee Wall Areas					
Attic					

Needs Correction:		
Replacement:		
_		
Notes:	 	



### **Quick Report/Pre-List Inspection**



Roofing

				<u> </u>	MOTH	<b>S</b>					
	Asphalt	Wood	Slate	Concrete/ Clay	Asbestos Cement	Metal	Corrugated Plastic	Built Up	Roll Roofing/ Mineral Surface	Modified Bitumen	Other
Main Slope											
Second											
Third											
Main Flat											
Second											
Dormer(s)											
Bay(s)											
Porch(es)											
Garage											
CHIMNEY(S):	□ Metal	□ Wood Over Metal	Stucco Over Metal	☐ Masonry Over Metal	Cement Asbestos	Masonry	☐ <b>M</b> utual	Partially Removed	Abandoned	None	
ROOF INSPECTION BY:	Binoculars	Ladder at Edge	□ Walk on	Drone							
INSPECTION LIMITED BY:	□ Snow/Ice/Wet	☐ Height	Access	☐ Fragile	Slope	Solar Panels	Gravel	Trees	Another Building		

Needs Correction:
Replacement:
The chimney caps should be checked & replaced
Notes: _The asphalt shingle is an 30 Yr Arch shingle installed 8-10 years ago

Remove old support cable





#### Quick Report/Pre-List Inspection

#### **Exterior**

GUITERS AND DOW	NSPUUIS.		WALL SUR	FACES.	RETAINING WALLS.
☐Integral/Built-In			Brick		□Wood
Aluminum			Stone		☐ Concrete
Galvanized Steel			□Block		□Stone
Plastic			☐Stucco/E	FIS (Synthetic Stucco)	☐Masonry
Copper				ingle Siding	Other
□Wood			☐Metal Sid	ling	
☐Discharge Below Gr	ade		☐Vinyl Sidi	ng	
☐Discharge Above Gr	ade		☐ Wood S	hingles	
			☐Asphalt S	Shingles	
LOT TOPOGRAPHY:			Asbestos	Cement Shingles	
∏Flat			☐Clay Shir	ngles	
☐Toward House			Slate		
☐Away from House			□Innsbruck	c Paper	
Ravine			Artificial S	Stone	
			☐Cement F	iber	
			□HardBoa	rd/OSB/Wafer-	
			Board/Inner		
LIMITATIONS:	Inspected and Working	Inspected and Not Working	Not Inspected	No Access/Concealed	NOTES:
Steps/Decks/Porches					1
Below Steps/Decks/Porches					
Grading					1
Exterior wall Finishes/Paint/Trim					
Garage					]
Garage Door Opener					]


Needs Correction:			
Replacement:			
			<del></del>
Notes:		 	



Panel Cover

## Checkpoint Home Inspection LLC 21 E Crescent Ave Ramsey NJ 07446 551-777-3774

Quick Report/Pre-List Inspection



#### **Electrical**

UTILITY:			MA	IN DISCON	NECT/SERVICE BOX:	Sì	STEM GROUNDING:
☐Service Drop, o	or			60 Amps			Water Pipe
☐Service Lateral			Ù	100 Amps			Ground Rod
SERVICE ENTRA	ANCE CABLE:		Ù	125 Amps			Ufer/Other
☐Copper, or			Ù	150 Amps			Not Visible
Aluminum				200 Amps			
☐SE Cable, or				uses		DI	STRIBUTION WIRE:
□ Conduit				Breaker			Metallic sheathed/BX
☐ Not Visible				No Main Disc	connect		Copper NM
Service Cap, o	r						Aluminum NM
Gooseneck			DIS	STRIBUTION	PANEL:		Copper Clad Aluminum
				uses			Solder-dipped Copper
SERVICE SIZE:				Bulldog/Push	matic		
☐60 Amps				Breaker		Ol	UTLETS:
☐100 Amps							Tested Yes  No
☐125 Amps			AU	XILIARY PA	NELS:		All Tested good
☐150 Amps			□F	uses			SeeNotes for Issues
☐200 Amps				Breakers			Mixed Grounded & angrounded
LIMITATIONS:	Not	Not	ı	Not			<u>g :                                   </u>
	Tested/Removed	Accessi	ble	Visible			
System Ground							
Fuse Blocks							
Main Service							
/Combination							

Needs Correction:
circuit breaker in the electrical panel that is overheating & needs attention. This was discovered during the infra
red inspection of the electrical panel. Please have a licensed Electrical contractor repair or replace the circuit
breaker.
The Outlet in the bathroom needs to be changed to a GFCI.
Replacement:
Notes:



**Quick Report/Pre-List Inspection** 



Heating

FUEL:			CHIMNEY LIN	NER:	EFFICENCY:
□Gas			None		☐Conventional ~60%
□Oil			Clay		☐High~>88%
☐ Electricity			Cement		☐Mid
□Wood			Required		Other
☐ Combination			Not Require	ed	
☐Oil-To-Gas Con	version		Metal		CAPACITY:
☐Electricity Radia	int Heat		☐Not Applica	ible	☐Input/Output (K BTU/Hr):
☐ Hot Water Radia	ant heat		Not Visible		
☐Forced Air Conv	ersion		Required for	or Conversion/Upgrade	
☐Heat Recovery	Ventilator				
Steam Boiler					
LIMITATIONS:	Inspected	Inspected	Not	No Access/Concealed	NOTES:
	and	and Not	Inspected		TOTES.
	Working	Working			_
Data Plate					
System Off					
AC or Heat					
Pump					
Heat Exchangers					
Oil Tank					
Chimney Clean-					
Out					
Chimney Liner					
Safety Devices					
Circulating Pump					_
Radiator/Zone					
Valves					
Humidifier					
Electronic Air					
Filter					
Solar Heating					

Notes:Vj g"j gc\pi "u\uvgo is a gas fired hot water boiler. It included the pressure relief value & proper piping to the bottom of the furnace approx 6 inch from floor. The home has steam radiators throughout the house. The heating system was off at this time as would be proper. The unit also has a proper clean out leg in the gas line, overflow & drain pipe.
Replacement:
Notes:

#### Boiler approval by Town 8/1/04





Quick Report/Pre-List Inspection

#### **Insulation / Ventilation**

Existing (R- Value/Depth)	Main Attic	2 <sup>nd</sup> Attic	3rd Attic	Main Flat	2 <sup>nd</sup> Flat	Cathedral	Knee Walls	Wood-Frame Walls	Wood-Frame Walls	Masonry Walls	Masonry Walls	Basement Walls	Crawl Space Walls	Crawl Space (Floor above)	Floor Above Porch	Log Walls
Not Accessible/Visible																
Glass Fiber																
Mineral Wool																
Cellulose																
Vermiculite																
Wood Shavings																
Plastic/Foam Board																
Duaru																

Air/Vapor Barrier	Roof Ventilation	Crawl Space Ventilation	Limited or Restricted Access
☐Plastic/Polyethylene	☐Ridge Vent	☐Wall Vent(s)	☐Crawl Space
☐Kraft paper	☐Roof Vent	☐Into Basement	☐Attic –
□ Not Visible	☐Gable Vent(s)	☐None Found	□Knee Wall Areas –
■None Found	☐Soffit Vent	Other	☐Floor Space –
Other	☐Turbine Vent		☐Attic Viewed From
	☐None Found		☐Crawl Space
	☐ Power Ventilator	·	☐Power Ventilator

Needs Correction:
Text here
Replacement:
Notes:
The attic space was visible from the hatch which was undersized at 18 X 20 approx. The visible
inspection from the hatch with a ladder was conducted & showed loose mineral wool insulation
inspection from the natch with a ladder was conducted & showed loose inflictal wool insulation
<del></del>



### Quick Report/Pre-List Inspection

Plumbing

SERVICE PIPE IN	ITO HOUSE:	WATER FLOW P	RESSURE:	WASTE PIPING IN HOUSE:	
Lead		Functional		☐Galvanized Steel	
☐Copper		☐Above Average		☐Cast iron	
Plastic		☐Below Average		□Plastic	
Galvanized Ste	el			Lead	
☐Not Visible		WATER HEATER	<b>:</b>	☐Copper	
		☐Combination Sy	ystem		
SUPPLY PIPING	IN HOUSE:	☐ Conventional		OTHER SYSTEMS:	
☐Galvanized Ste	el	☐Induced Draft/F	an Assisted	☐Solid Waste/Ejector Pump	
Plastic		☐Tankless/Indire	ct/Instantaneous	☐Sump Pump	
☐Copper		Electric		☐Laundry Tub Pump	
Brass		□Gas			
☐Not Visible		□Oil		Main Water Shut-off:	
		☐High Efficiency-	-Side Vented	Main Gas Shut-off:	
☐ Public supply	Well Supply	☐Tank Capacity:			
LIMITATIONS:	Inspected	Not Inspected	Not Visible or NONE		
	and/or Working				
Water					
Gas					
Septic System					
Water Treat.					
Equipment					
Main Shut-off		П			
Valve				_	
Tub/Sink					
Overflows					
Fixtures Not		Toilet □Sink □Shov			
Tested/Not in	│ □Hot Tub □Whirlp				
Carviace					

Notes:			
Replacement:			



## Quick Report/Pre-List Inspection



#### **Interior**

<b>MAJOR WALL FI</b>	NISHES:		<b>MAJOR CEIL</b>	ING FINISHES:	WINDOWS Type & Tested
□Plaster			□Plaster		☐Single/Double Hung
□Drywall			□Drywall		☐ Casement
Paneling			☐Acoustic Ti	le	□Sliders
☐Brick/Stone			Suspended	l Tile	☐Awning
☐Concrete/Conc	rete Block		Metal		□Fixed
☐Stucco/Texture	/Stipple		☐ Stucco/text	ured/Stipple	Skylights
FIREPLACES:			□Wood		Solariums
Masonry					GLAZING:
Zero Clearance	)		PARTY (Fire)	WALLS:	Single
_					
□Insert			☐Masonry		□Double
□Gas			☐Wood Fran	ne	□Triple
□Coal			□None in Attic		☐Primary Plus Storm
☐Roughed-In			□ Not Visible /	/Accessible	
☐Non-Functional					
☐Wood Stove					
□None					
LIMITATIONS:	Inspected and Working	Inspected and Not Working	Not Inspected	Finished/Concealed	NOTES:
CO Detectors					
Security					
Systems	Ш				
Intercoms					
Central vacuum					
Chimney Flues					
Chimney Draw					
Flevators					

Needs Correction:		
Replacement:		
Notes:	 	



#### **Quick Report/Pre-List Inspection**

#### **AC / Cooling / Heating**

AIR CONDITIONIN	G:		Energy Sour		NOTES:
☐Air Cooled			☐ Heat ☐ C	il □Gas □ Elec □other	
			Air 🗌 Oi	il □Gas □ Elec □other	
☐ Window Unit Sys	stems				
☐Gas Chiller			OTHER SYST	ΓEMS:	<u> </u>
			☐House Fan		<u> </u>
HEAT PUMP:			Evaporative	e Cooler One Speed	<u> </u>
☐Air Source			Evaporative	e Cooler Two Speed	<u> </u>
Auxiliary Heat					<b>∐</b>
☐Ground/Water So					<b>∐</b>
☐Independent Unit	t				
LIMITATIONS:	Inspected and Working	Inspected and Not Working	Not Inspected	No Access/Concealed	
Data Plate			П		1
System Off					7
Outdoor Coil					7
Outdoor Temp. Prevented Operation			•		
Cooling Mode Test					
Heating Mode Test					
Heat Gain					
House Fan					
Window AC Unit					

			The following is ntial Water Issue	a list along with a	guide to the
<ul><li>Co2 Detector</li><li>Fire alarm v</li></ul>	or in the living twired to electric	ting room al system airs	 		
•					
				elp the homeowner eval a life safety issue befor	
of the home. The Price\$ 299		Fast Paced inspection	on walk-through with c	heck Off report & Minin	nal pictures. <b>Initial</b>
B) Initial for Optiona	<u>al -</u> Radon-\$169	:Infrared Came	ra use-\$95 : Ta	ank Sweep-\$235	WDI-\$125
defects and deficiencies the inspector upon ordin not the intent, nor will t systems and component garages/carports/decks/structures unless explici at the client's risk for pe performed and prepared transferable. Systems ar electrical, attic, interiors LIMITS OF THE INSP home. The inspector will	of the inspected syst hary visual observation he inspection report it is of the primary premaporches/pations. The interest of the client resonal injury or damant for the sole, confidered components to be interest, but the components of the compon	tems or and component. Minor and cosmetic identify and list all minises. Included with the aspection does not incent is encouraged to accept to person or propential, and exclusive us an aspected include exponent, basement and critical is limited to the rear move equipment, sy other items to conductive.	nts which existed at the too defects may be listed in an and cosmetic defects the inspection is the evaluation of detach company the inspector durity for any reason or from and possession of the cosed and visible foundation awaspaces, heating and coadily accessible and visits stems, furniture, appliance this inspection or other	ion of the home and identified of the inspection and the report for maintenants. 2 The inspection is interaction of primary attached and garages/carports/pationing the inspection. Client any cause. The inspection and structures, exterior entral air conditioning, arible systems, equipment a ces, floor coverings, finis twise to expose concealed	I which are evident to ce purposes, but it is nded to evaluate  os/decks or other t participation shall be on and report are eport is not ors, roofing, plumbing, and garage or carport. and components of the hed or fastened
Customer		_ E Mail			
Address					
City	State	Zip	Date		
Permission to E I 2ND:			People		
Customer Signat	ure:	<del></del>	Date		
Checkpoint Sign			Date	Vers	ion 21521-V1